DMV Lane Technician Observation Report

DMV Technician: John fashwalu P	MV Technician: Toka - Lashacha Position; Lot 2			
Station: Wilming You Date: 7-18-14 Time: 2:36				
Vehicle Make: Aordo Model Model Year				
GVWR: Fuel Type: 6 A S Registration Number: Pc 150225				
Auditor Coverd 14 / ce Covert Overt (Circle One)				
	Y	ES	NO	N/A
1. Did technician check vehicle paper work and verify VIN num	ber?	1		
2. Was Emissions testing required?		/		
a) Was Emissions testing performed using OBD?				
b) Was Emissions testing performed using Analyzer Probe?				
c) Was Emissions testing performed using Paddle(s)?	153			
d) Was Emissions testing performed using Clip?				
3. Was Catalytic Converter inspection required?				4
a) Was Catalytic Converter inspection performed?				
4. Was Fuel Tank pressure testing required?				-
a) Was Fuel Tank pressure testing performed?				
5. Was Fuel Cap pressure testing required?				
a) Was Fuel Cap pressure testing performed?				
6. Is this test a Re-check from a prior failure?			2	
a) Which re-check test is being performed? 1 2 3 (circle on				
b) If this is re-check #3, was repair paperwork verified for wa	iver?			
Sussex County Only				
7. Was Curb Idle testing required?				
a) Was Curb Idle testing performed?				
Comment:				

Original 08/06/2009/TMP